



Title: WIRING DIAGRAM VAX31


PART	COMBINATION OF OUTPUT CONTACTS	OUTPUT CONTACTS TO TERMINALS			
		NORMALLY OPEN		CHANGE OVER CONTACT	
001	2M 2C/O	7 - 8	19 - 20	2 - 1 - 6	4 - 3 - 5
		M	M	BBM	BBM



COMMERCIAL COPY

TERMINALS			
	COM (-)	110 (+)	220 (+)
RLA	10	9	14
RLB	12	11	15
C-UNIT	17	18	16

Z CASE DETAILS



TERMINAL POSITIONS VIEWED FROM FRONT

CONTACT DESCRIPTION

M: MAKE
B: BREAK
C:CHANGE OVER CONTACT (BBM)

23/07/2014